

2014–2018 BMW X5 and 2015–2018 BMW X6 Blower Motor Equipped with Resistor: 2312001


gpd

Global Parts Distributors, LLC

TECH TIP

A common reason for blower motor failure is a faulty blower motor resistor. The blower motor resistor controls the speed of the blower motor to reduce/increase air flow based on A/C control commands. Most blower motors do not come equipped with the blower motor resistor; it is usually purchased separately. It is best practice to check/replace the blower motor resistor and connector/relay when replacing the blower motor. Considering the time to replace a blower motor takes approximately 2–3 hours, making these replacements a nominal cost and easy preventative measure.

gpd blower motor #2312001 for 2014–2018 BMW X5 and 2015–2018 BMW X6 comes fitted with the blower motor resistor.



Refer to Tech Tip #143 “gpd Blower Motors Vs. Competitors” for more information about gpd blower motors.

#161

gpdtechtips.com