

[Title]

Belt Tensioner #4011375

gpd

Global Parts Distributors, LLC

TECH TIP

- '03-'05 Van Express/Chevy Savana • '03-'05 Chevy Trailblazer/Envoy
 - '00-'07 Chevy Tahoe/Yukon/Denali
 - '00-'05 Chevy Suburban • '05 Chevy SSR
- '99-'06 Chevy Silverado/Sierra • '01-'02 Chevy Denali
- '02-'04 Chevy Avalanche • '02-'06 Cadillac Escalade

A “rattling” noise coming from the hood of any of the applications listed in this tech tip may be caused by the belt tensioner.

If the compressor failed due to liquid slugging, it will cause premature failure of the belt tensioner. If the belt tensioner and serpentine belt are not replaced at the same time, it may generate a “rattling” noise under the hood. This noise can be mistaken for a premature compressor failure. The typical life of a belt tensioner is 60,000 miles.

Some common causes for the replacement of the belt tensioner are

- Loss of tension
- Bad bearing
- Damaged pulley

gpd offers a replacement belt tensioner for the applications listed above.



gpd # 4011375

#22

gpdtechtips.com

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)