


Have you experienced an issue with the blower motor speed selection on a Ford Ranger 1983–2005?

Have you experienced an issue with the blower motor speed selection on a Ford Ranger 1983–2005, or Explorer 2002–2005? The most likely problem is the blower motor resistor has failed and will require replacement. Another common problem is the electrical connector to the blower motor resistor may have a short causing the socket connection to melt.



The 1712270 is a replacement electrical connector that can be used to replace the burnt socket. Using the information below, you can cut out the old electrical connector and crimp this in its place.



The 1711725 directly fits the front blower resistor both the manual and the automatic air conditioning systems. It has a two hole mount.

