

Dodge Ram Liquid Line



Did your original liquid line on your 1994–2002 Dodge Ram come with a low pressure service connection and now the replacement now comes with a high pressure service connection? (gpd part number 4811583 (1994–2002))

After a factory redesign, a change was made to the service port located before the orifice tube on the liquid line. This change should not be a reason for concern. The replacement hose manifold assembly that bolts to the compressor has a low side service port.

Manifolds:

4811565

- 1994 5.2 V8
- 1995 5.2 V8
- 1996 5.2 V8, 5.9 V8
- 1997 5.2 V8, 5.9 V8



4811771

- 1994 5.9 Diesel
- 1995 5.9 Diesel
- 1996 5.9 Diesel
- 1997 5.9 Diesel



4811853

- 1994 3.9 V6, 5.9 V8, 8.0 V10
- 1995 3.9 V6, 5.9 V8, 8.0 V10
- 1996 3.9 V6, 8.0 V10
- 1997 8.0 V10



4811770

- 1998 5.9 Diesel
- 1999 5.9 Diesel
- 2000 5.9 Diesel
- 2001 5.9 Diesel
- 2002 5.9 Diesel



4811563

- 1998 5.2 V8, 5.9 V8, 8.0 V10
- 1999 5.2 V8, 5.9 V8
- 2000 5.2 V8, 5.9 V8
- 2001 5.2 V8, 5.9 V8
- 2002 5.9 V8



Exception: This liquid line does have a low side port***

4811566

- 1997 3.9 v6



4812140

- 1994 5.9 Diesel
- 1995 5.9 Diesel
- 1996 5.9 Diesel
- 1997 5.9 Diesel

