



Saturn Compressor



gpd #7512025



gpd #5512025

This Saturn compressor has an internal thermostatic control valve.

When charging the system thru the low side, the thermostatic control valve **will** freeze open and will not allow the compressor to pump, which leads the installer to believe that the compressor has failed.

* To charge the system properly, the Freon must be pumped in on the HIGH side using a charging machine with the engine off.