

Saturn SC/SL/SW/LS/LW Series

Compressor: 6512025



The 1999–2002 Saturn SW/SL/SC/LS/LW models listed below feature a compressor with an internal thermostatic control valve. When charging the system thru the low side, the thermostatic control valve will freeze open and will not allow the compressor to pump, which may lead the installer to believe that the compressor has failed.

- 2000–2001 Saturn LS
- 2000–2002 Saturn LW
- 1999–2002 Saturn SL/SC
- 1999–2001 Saturn SW



6512025

To charge the system properly for these Saturn applications, refrigerant must be pumped in on the HIGH side using a charging machine with the engine off.