

Extend the Life of Your Condenser



Global Parts Distributors, LLC

TECH TIP

As described in gpd Tech Tip #1, late model multi-flow/parallel flow condensers cannot be flushed. They must be replaced. These newer condensers are designed with many small passages for more efficient cooling compared to past designs. Although more efficient, parallel flow condensers are more susceptible to debris and getting clogged, which can lead to premature failure. Vehicles that have not been started in a long time or stored outside are more likely to experience premature failure due to excess debris restricting air flow to cool the system and passengers.

Before diagnosing an A/C system/ condenser, be sure to clear any surrounding debris, dust, trash, etc.



Extend the life of your condenser by cleaning out excess debris surrounding the system.



A cause of premature condenser failure is excess debris in and/or surrounding the condenser.

#34

gpdtechtips.com

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)