

1992–2002 Dodge Ram Suction/Discharge Hose Manifold Lines: 4811565, 4811853, 4811563, 4811566, 4811771, 4811770, and 4812140

Due to model updates, select 1992–2002 Dodge Ram liquid lines have been redesigned. The low side service port on first generation designs was located on the liquid line. Second generation designs now feature the high side service port on the liquid line (4811583).

The gpd suction/discharge replacement hose manifolds listed below bolt directly to the compressor and feature the low side service port on the suction line.



4811583 • 1994–2002 Dodge Ram
Liquid Line with High Side Service Port
and Orifice Tube

4811565

- 1994 5.2 V8
- 1995 5.2 V8
- 1996 5.2 V8, 5.9 V8
- 1997 5.2 V8, 5.9 V8, 8.1 V10



4811771

- 1994 5.9 Diesel
- 1995 5.9 Diesel
- 1996 5.9 Diesel
- 1997 5.9 Diesel



4811853

- 1994 3.9 V6, 5.9 V8, 8.0 V10
- 1995 3.9 V6, 5.9 V8, 8.0 V10
- 1996 3.9 V6, 8.0 V10



4811770

- 1998 5.9 Diesel
- 1999 5.9 Diesel
- 2000 5.9 Diesel
- 2001 5.9 Diesel
- 2002 5.9 Diesel



4811563

- 1998 5.2 V8, 5.9 V8, 8.0 V10
- 1999 5.2 V8, 5.9 V8
- 2000 5.2 V8, 5.9 V8
- 2001 5.2 V8, 5.9 V8
- 2002 5.9 V8



4812140

- *Liquid Line with Low Side Service Port*
- 1994 5.9 Diesel
- 1995 5.9 Diesel
- 1996 5.9 Diesel
- 1997 5.9 Diesel



4811566

- 1997 3.9 V6