


# 2008–2011 Ford Escape/ Mercury Mariner Blower Motor Speed Selection Troubleshoot



Experiencing an issue with the blower motor speed selection on a 2008–2011 Ford Escape or Mercury Mariner? The most likely problem is the blower motor resistor has failed and will require replacement. These are a common problem on this vehicle. It is always best to check the electrical connection/ blower motor resistor pigtail for signs of burning between the resistor and the pigtail. This could be a sign that there is another issue with the electrical circuit.



1712398  
2008–2012 Ford Escape;  
2008–2011 Mercury Mariner;  
Blower Motor Resistor;  
Automatic AC



1712209  
2008–2012 Ford Escape  
Blower Motor Resistor; Manual A/C



1712341  
2008–2012 Ford Escape; 2008–2011 Mercury Mariner  
Blower Motor Resistor Pigtail; Electrical Connector w/ Waterproof Butt Connectors