

2004–2008 Ford F-150 and 2006–2008 Lincoln Mark LT Accumulator: 4811600



Global Parts Distributors, LLC


TECH TIP

#119

gpdtechtips.com

Not all accumulator replacements are the same. Some Ford accumulators are designed with a protective cover around the accumulator. This protective cover is often ignored by aftermarket air conditioning suppliers. To save customers time and money, gpd has included the protective cover around the accumulator for the applications listed above.

The protective cover on the accumulator for these vehicles helps reflect heat from the engine bay and functions as a mount. Over time, the plastic can get brittle when subjected to heat and vibration within the engine bay. The protective cover is held together by spring steel clips that often get lost during replacement. The cover may also be unusable if the mounts break off. The plastic covering, by itself, would need to be purchased directly from a dealer. Save time and money with gpd's direct replacement accumulator 4811600.



Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)