Radiator (1517C) Service Notice for 1994–1996 Buick Roadmaster, Cadillac Fleetwood, and Chevrolet Caprice/Impala SS

Due to model updates, there are variations in radiator replacements for 1994–1996 Buick Roadmaster, Cadillac Fleetwood, Chevrolet Caprice, and Chevrolet Impala SS models (part #1517C).

• The original, 1st generation, radiator design can be identified by two outlets on the coolant tank reservoir; one connected to the heater and the other to the radiator. This design was changed due to a frequently reported issue with the heating system. When the heater was turned on, the coolant was not reaching the required temperature to heat the vehicle cabin. The two-outlet coolant tank design essentially hindered heating performance because it allowed a constant flow of water into the coolant circuit. In April 1994, GM released a service bulletin, 'GM TSB 431214', with instructions on how to modify the original reservoir tank with a rubber boot over one of the outlets and a T piece in the heater circuit to prevent leaking from the second outlet connected to the radiator. With this modification, coolant is able to reach the required temperature to heat the vehicle cabin.



• Most aftermarket replacement radiators feature the 2nd generation design, with only one outlet on the coolant tank reservoir to the heater. These radiators are designed without an outlet to the reservoir tank.



#190

gpdtechtips.com

Many of the 1st generation vehicle models on the road today have a modified coolant circuit as described above. Please refer to GM TSB 431214 (April 1994) for proper modification procedure and gpd Tech Tip #2 'Flush Procedure'. Please note to remove excess air from the system at the bleed nipple located near the throttle body on the passenger's side.

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)