

2003–2011 Saab 9–3 Blower Motor and Blower Motor Resistor Options: 2311920, 2312034, 1712870, and 1712873



gpd offers two blower motor and blower motor resistor options for the 2003–2011 Saab 9–3 2.0 and 2.8 engine models listed below depending on whether the vehicle has automatic or manual A/C controls. These blower motors and blower motor resistor options have different internal electronics and do not interchange.

How to identify which blower motor resistor option is correct?

- Determine if the vehicle has manual or automatic climate control (Refer to gpd Tech Tip #112 for a depiction of manual vs. automatic climate controls).
- Look under the passenger’s side of the vehicle where the blower motor is located, pointing downward toward the floor.
- The blower motor resistor will be located beside the blower motor, towards the kick panel.



Front View



Rear View

2311920 • Blower Motor
Without Resistor Port
Automatic A/C



1712870 • Blower Motor Resistor
Automatic A/C



Front View



Rear View

2312034 • Blower Motor
With Resistor Port
Manual A/C



1712873 • Blower Motor Resistor
Manual A/C

#218

gpdtechtips.com

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)