

2003-2006 Chevrolet Silverado Blower Motor Options: 2311654 and 2311598

There are two gpd blower motor replacement options for the 2003–2006 Chevrolet Silverado due to a change in style during production. There are key differences between these blower motors that can be identified by looking at how the blower motor is mounted into the system.

• 2311654 will have a "turn in flange". This blower motor has a twist and lock-in style motor housing.





• 2311598 will have a "bolt-on flange". This blower motor has a bolt-in style motor housing.





#152

gpdtechtips.com

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)