

2010–2014 Ford Mustang Blower Motor Resistor Options: 1712398 and 1712040

Sometimes vehicle components are updated in the process of introducing a new model. gpd offers two blower motor resistor options for the 2010–2014 Ford Mustang models listed below depending on whether the vehicle has automatic or manual A/C controls. These blower motor resistor options have different internal electronics and do not interchange.

How to identify which blower motor resistor option is correct?

- Determine if the vehicle has manual or automatic climate control (Refer to gpd Tech Tip #112 for a depiction of manual vs. automatic climate controls).
- Look under the passenger’s side of the vehicle where the blower motor is located, pointing downward toward the floor.
- The blower motor resistor will be located beside the blower motor, towards the kick panel.



1712040;
Manual A/C

Ford Mustang Applications:

- 2005–2007 4.0 V6; 4.6 V8
- 2007–2010 4.0 V6; 4.6 V6; 5.4 V8
- 2011–2012 3.7 V6; 5.0 V8; 5.4 V8
- 2013–2014 3.7 V6; 5.0 V8; 5.8 V8



1712398;
Automatic A/C

Ford Mustang Applications:

- 2011–2014 3.7 V6; 5.0 V8; 5.8 V8