2000–2005 Ford Excursion, 1999–2007 Ford F-Series Super Duty, and 2007 Ford Econoline Accumulator: 1411655

Not all accumulator replacements are the same. Some Ford accumulators are designed with a protective cover around the accumulator. This protective cover is often ignored by aftermarket air conditioning suppliers. To save customers time and money, gpd has included the protective cover around the accumulator for the applications listed above.

The protective cover on the accumulator for these heavy-duty vehicles helps to reflect heat from the engine bay and functions as a mount. Over time, vibration and heat can cause the plastic mounts to break. The metal retaining clips are prone to fly off when removing the plastic cover. There is also a wire loom lock clip on the top of the accumulator's protective cover that can break if not handled carefully. The plastic covering, by itself, would need to be purchased directly from a dealer. Save time and money with gpd's direct replacement accumulator 1411655.



Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)

#118

gpdtechtips.com