## **Competitor Comparison:**

gpd Compressor 6512232

There are many possible reasons for compressor failure: lack of lubrication, excess debris, burnt clutch, etc. One of the ways gpd helps consumers avoid premature failure is by pre-filling all 65 series compressors with the system's specified amount of oil, gpd also designs parts to meet or exceed OE design, fit, form, and function. Some aftermarket suppliers may cut corners on design to offer a bargain price, to the point where some do not even look like the OE style.

Compared to competitors, gpd's compressor 6512232 is designed to look and fit like the original compressor style for ease of replacement. Looking and fitting like the compressor that was originally replaced gives customers confidence in the purchase of a quality aftermarket replacement.



#138

gpdtechtips.com

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)