

2005 Ford Excursion 6.0 V8 Diesel Engine Radiator Replacement Options: 2741C & 2887C

gpd offers two radiator replacement options for the 2005 Ford Excursion 6.0 V8 diesel engine model with key differences in fitting connections.

- Radiator 2741C is suited for 2005 Ford Excursion models with a 6.0 V8 diesel turbo engine with automatic transmission connections featuring a threaded connection fitting style. To identify this model, visually examine the vehicle for a large brass nut attached to the radiator tank where the transmission lines connect at the bottom of the radiator.
- Radiator 2887C is suited for 2005 Ford Excursion models with a 6.0 V8 diesel turbo engine with automatic transmission connections featuring a quick connect fitting style. To identify this model, visually examine the vehicle for a plastic case/holder over the transmission line connections at the bottom of the radiator.





2741C • Radiator 3/4" Transmission Oil Cooler Threaded Fitting Style

2887C · Radiator

Quick Connect Transmission

Oil Cooler Fitting Style

#219

gpdtechtips.com

gpd recommends the use of a transmission line quick disconnect tool when disconnecting the transmission lines on a radiator with quick connect style fittings.

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure, or distribution is prohibited. Global Parts Distributors, LLC (gpd) accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)