

2011–2019 Ford Explorer 3.5L Engine Hose Discharge Line Options: 4812855, 4813485, 4813364, and 4813365

There are four gpd hose discharge line replacement options for 2011–2019 Ford Explorer 3.5L engine models depending on whether the vehicle is equipped with or without a turbo engine. 4812855, 4813485, 4813364, and 4813365 are not interchangeable.

- gpd 4812855 is a hose discharge line without turbo for 2011–2015 models.



4812855
Naturally Aspirated

- gpd 4813485 is a hose discharge line with turbo for 2013–2019 models.



4813485
Turbocharged, 4WD

- gpd 4813364 is a hose discharge line without turbo for 2016–2019 models.



4813364
FWD

- gpd 4813365 is a hose discharge line without turbo for 2016–2019 models.



4813365
AWD

