

2013–2015 Ford Explorer 3.5 V6 Engine Discharge Hose Line Options: 4812855 and 4813485



Global Parts Distributors, LLC

TECH TIP

#248

gpdtechtips.com

There are two gpd hose discharge line replacement options for 2013–2015 Ford Explorer 3.5 V6 engine models depending on whether the vehicle is equipped with or without a turbo engine. 4812855 and 4813485 are not interchangeable.

- gpd 4812855 is a discharge hose line for naturally aspirated engine models.



4812855
Hose Discharge Line; Naturally Aspirated

- gpd 4813485 is a discharge hose line for turbocharged engine models.



4813485
Hose Discharge Line; Turbocharged