

White Dust Blowing from Air Vents?

gpd

Global Parts Distributors, LLC

TECH TIP

During production, the evaporator is coated with a protective laminate that can wear off over time. If a solid white powder/dust is blowing through the A/C vents into the passenger cabin, it is most likely residue from this laminate blown by the blower motor. It can also be an excess of flux used in the manufacturing process. This is not to be confused with a white colored cold mist that can be blown into the cabin by a frozen evaporator.

We recommend consulting an expert to assess the A/C system and decide if the evaporator needs to be replaced. While it is most likely laminate residue, there is a chance the source is debris or chemicals from another component.



#158

gpdtechtips.com

Manufacturer names, logos and part numbers are for reference only. All prices, taxes and availability are subject to change without notice. This document and any files transmitted with it are confidential and intended solely for the use of the individual or entity to which they are addressed. If you have received this document in error, please delete it immediately. Note that any views or opinions presented in this document are solely those of the author. Any unauthorized review, use, disclosure or distribution is prohibited. gpd accepts no liability for any damage caused by any virus or other means transmitted by this document. © Global Parts Distributors, LLC (gpd)